
### **Flashing Laps**

FL01/AA, Post Hung Deluxe Eave Flashing FL02/AA, Universal Rake Flashing FL03/BA, High Side Eave Flashing FL03/GA, High Side Eave Flashing FL03/SA, High Side Eave Flashing FL04A/AU, Roof to Wall Flashing FL05/AA, Universal Roof to Wall Flashing FL06/AA, Flashing Laps and Transitions - General Requirements FL07/AA, Valley Gutter Lap & Endcap Fastener Detail FL07W/AA, Valley Gutter Flashing FL08A/AB, Inside Corner Flashing FL08A/AC, Inside Corner Flashing FL08A/AW, Inside Corner Flashing FL08/AB, Outside Corner Flashing FL08/AC, Outside Corner Flashing FL08/AW, Outside Corner Flashing FL09/AA, Standard Gutter FL09A/AA, Oversize Gutter FL11/AA, Valley Flashing Lap Detail FL12/GA, Cleated Rake Flashing FL12/SA, Cleated Rake Flashing FL13/GA, Cleated High Side Eave Flashing FL13/SA, Cleated High Side Eave Flashing FL14/AA, Eave Closure Flashing FL15/AA, Special Roof to Wall Flashing NP20/AA, Parapet Cap Flashing RC33A/GA, Hip Trim Lap RC33A/SA, Hip Trim Lap RC33/GA, Expansion/Vented Ridge/Hip Flashing Lap RC33/QR, Expansion Ridge/Hip Flashing RC33/SA, Expansion/Vented Ridge/Hip Flashing Lap RC35A/AA, Section Through Roof Flashing Lap RC35W/AA, Exposed Roof Flashing Fastener Requirement WFL08/AB, Outside Corner Flashing




Post Hung Deluxe Eave Flashing Standard Flashing Lap FL01/AA



Download the DWG file by clicking here.



Universal Rake Flashing All Roof Panels FL02/AA




Download the DWG file by clicking here.

**To Section Index** 

Revised 10/5/20




High Side Eave Flashing Long Span III FL03/BA



Download the DWG file by clicking here.



High Side Eave Flashing Loc Seam Roof FL03/GA




Download the DWG file by clicking here.

**To Section Index** 

Issued 9/28/2016




High Side Eave Flashing Standing Seam FL03/SA



Download the DWG file by clicking here.




Roof to Wall Flashing At High Side Condition FL04A/AU



Download the DWG file by clicking here.



Universal Roof to Wall Flashing At Rake Conditions FL05/AA



Download the DWG file by clicking here.

**To Section Index** 

Issued 9/28/2016



Flashing Laps and Transitions - General Requirements

FL06/AA

ROOF FLASHING LAPS AND END TRANSITIONS EXPOSED TO ROOF CONDITIONS

- 1. ROOF FLASHING LAPS SHALL BE SEALED WITH 3/4 X 3/16 TAPE MASTIC (3/4 TM).
- 2. FIELD CUT FEB-10.2 BACKUP FLASHING TO REINFORCE FLASHING ENDLAPS AND TERMINATIONS. INSTALL FEB AS SHOWN IN CONNECTION DETAILS (INBOARD) OF MASTIC, CLOSURES AND SUPPORT MEMBERS.

EXTRA CARE SHOULD BE TAKEN: <u>DO NOT EXTEND FEB INTO THE MASTIC</u> <u>DO NOT EXTEND FEB BEYOND THE BUILDING ENVELOPE</u>

FEB EXTENDED BEYOND THE BUILDING ENVELOPE INTERUPTS THE GASKET CREATED BY THE CONTINUOUS MASTIC APPLICATION. ADJUST FIELD CUT FEB LENGTHS AS REQUIRED.

- STANDARD FASTENER SPACING AS SHOWN ON CONNECTION DETAILS WILL NEED TO VARY TO ENSURE A COMPLETE GASKET SEAL AT SOME LOCATIONS. INCLUDING (BUT NOT LIMITED TO) THE FOLLOWING.
  - DECREASE STITCH FASTENER SPACING FROM 6" O.C. TO 3" O.C. AT FLASHING LAPS AND TRANSITIONS.

EXAMPLES: RIDGE FLASHING TO RAKE CAP HIP FLASHING TO TRCZ AT EAVE RIDGE CAP TO PEAK BOX

 AT ALL EXPOSED ROOF FLASHINGS ENDLAPS INSTALL A STITCH FASTENER THROUGH THE UPPER FLASHING 2 1/2" FROM THE ENDLAP.
SEE DETAIL: RC35WAA

- 4. VALLEY GUTTER LAPS SHALL BE SEALED WITH 2 X 3/16 TAPE MASTIC (2 TM) AND SHALL BE STITCHED WITH #14 ROOF FASTENERS 2" ON CENTER. QUANTITY WILL VARY WITH GUTTER SIZE.
- 5. PREDRILL 1/4"Ø HOLES AT UPPER AND LOWER FLASHING FOR #14 FASTENERS. DO NOT PREDRILL FEB BACKUP FLASHING.
- FOR ROOF FLASHING LAPS NOT SHOWN IN DETAILS, THAT ARE EXPOSED TO ROOF CONDITIONS, USE THE FOLLOWING AS A GUIDE;
  - REINFORCE THE TOP SIDE OF ALL FLASHING END TRANSITIONS EXPOSED TO ROOF CONDITIONS USING #14 ROOF FASTENERS, 3" ON CENTER THROUGH MASTIC AND FIELD CUT FEB-10.2 (AS SPACE ALLOWS)

FLASHING LAPS NOT SHOWN AND NOT EXPOSED TO ROOF CONDITIONS

- 7. FOR FLASHING LAPS NOT SHOWN AND NOT EXPOSED TO ROOF CONDITIONS, USE THE FOLLOWING AS A GUIDE;
  - USE I/8 INCH BLIND RIVETS 3" ON CENTER.

#### GENERAL REQUIREMENTS


8. ALL FLASHING LAPS SHALL BE TWO INCHES.

FLASHING LAPS AND TRANSITIONS – GENERAL REQUIREMENTS FLO6

Download the DWG file by clicking here.




Valley Gutter Lap & Endcap Fastener Detail Long Span III, Standing Seam, & Loc Seam FL07/AA



Download the DWG file by clicking here.



Valley Gutter Flashing Long Span III, Standing Seam & Loc Seam FL07W/AA




Download the DWG file by clicking here.

**To Section Index** 

Revised 9/30/2017



Inside Corner Flashing Long Span III Walls FL08A/AB




Download the DWG file by clicking here.






Inside Corner Flashing Architectural III or Architectural "V" Rib Walls FL08A/AC



Download the DWG file by clicking here.




Inside Corner Flashing Insulated Wall Panels FL08A/AW



Download the DWG file by clicking here.



Outside Corner Flashing Long Span III Walls FL08/AB




Download the DWG file by clicking here.






Outside Corner Flashing Architectural III or Architectural "V" Rib Walls FL08/AC



Download the DWG file by clicking here.



Outside Corner Flashing Insulated Wall Panels FL08/AW




Download the DWG file by clicking here.



Standard Gutter

FL09/AA




Download the DWG file by clicking here.



Oversize Gutter


FL09A/AA



Download the DWG file by clicking here.




Valley Flashing Lap Detail Standing Seam & Loc Seam Roof Panels FL11/AA



Download the DWG file by clicking here.




Cleated Rake Flashing Loc Seam Roof FL12/GA



Download the DWG file by clicking here.



Cleated Rake Flashing Standing Seam FL12/SA




Download the DWG file by clicking here.

**To Section Index** 

Issued 9/28/2016




Cleated High Side Eave Flashing Loc Seam FL13/GA



Download the DWG file by clicking here.




Cleated High Side Eave Flashing Standing Seam FL13/SA



Download the DWG file by clicking here.




Eave Closure Flashing Standard Flashing Lap FL14/AA



Download the DWG file by clicking here.



Special Roof to Wall Flashing At Rake Condition FL15/AA




Download the DWG file by clicking here.

**To Section Index** 

Issued 9/28/2016




Parapet Cap Flashing Non-Structural Parapets NP20/AA



Download the DWG file by clicking here.




Hip Trim Lap Loc Seam Roof With THFC\_ or THCHC\_ RC33A/GA



Download the DWG file by clicking here.



Hip Trim Lap Standing Seam Roof With THFS\_ RC33A/SA






**To Section Index** 

Issued 9/28/2016



Expansion/Vented Ridge/Hip Flashing Lap Loc Seam/Long Span III Roofs and Ridge Cap RCLS\_ RC33/GA




REF. DETAILS FL06AA, RC35AAA & RC35WAA

Download the DWG file by clicking here.




Expansion Ridge/Hip Flashing Insulated Roof Panels RC33/QR



Download the DWG file by clicking here.



Expansion/Vented Ridge/Hip Flashing Lap Standing Seam Roofs and Ridge Cap RCSS\_ RC33/SA




Download the DWG file by clicking here.



Section Through Roof Flashing Lap

RC35A/AA




Download the DWG file by clicking here.



**Exposed Roof Flashing Fastener Requirement** 


RC35W/AA



Download the DWG file by clicking here.



Outside Corner Flashing Long Span III Walls WFL08/AB



Download the DWG file by clicking here.